

Home Inspections, Inc.

# The Most Advanced Home Inspection In The World

36 E. Tacoma Ave Latrobe, PA 15650 (724)836-0328 (724)836-1842

## One Call Does It All

# Home Inspection Report

Computerized for the most complete and comprehensive report available

PREPARED EXCLUSIVELY FOR:

## **Property:**



Only an ASHI inspector can provide you with a professional inspection that combines 42 years of nationally recognized technical standards along with a code of ethics and the very best in customer service, education and satisfaction.

WWW.ASHI.ORG

# **ASHI Inspector**

#263647 Christopher A. Thomas

## **Table of Contents**

BASIC INFORMATION	
SCOPE OF INSPECTION SERVICES	3
INSPECTION STANDARDS	
EXPLANATION OF TERMS	4
NOT A WARRANTY	
MINE SUBSIDENCE	
INSPECTION FINDINGS	6
NOTE:	
Kitchen	
Bathroom	-
Bathroom	
Windows	
Attic	
Garage	
Basement Foundation	
Laundry	
Water Heater	
Heating System	-
Air Conditioning	
Electrical Service	
Plumbing	
Utility Services	
Fire Place / Wood Stove	
Environmental Survey	
Building Perimeter Exterior	
Patios / Decking / Porches	
Roof	
Structure	
GENERAL REMARKS AND SUGGESTIONS:	
WELL FLOW TEST REPORT	
PRIVATE WASTE DISPOSAL SYSTEM INSPECTION CHECKLIST	
SUMMARY OF POTENTIAL CONCERNS	
NOTE:	
SKETCH OR PICTURES	

## **Basic Information**

This report contains confidential information	This report contains confidential information and is supplied solely for use by					
Client Information:						
Showing Agent	Listing Agent					
Lee Faiel	Property:					
Christopher A. Thomas	Date					

Weather: Order Number:



## Scope of Inspection Services

YOU ARE ADVISED TO READ THIS SCOPE OF INSPECTION SERVICES CAREFULLY. IF YOU HAVE ANY QUESTIONS, YOU SHOULD CONTACT THIS INSPECTION SERVICE IMMEDIATELY.

### 1. Scope of Inspection:

The scope of this inspection ("Scope") is limited to the visual examination of the safety and readily accessible portions of the structure and permanently attached kitchen appliance systems and components. No other systems, items or appliances are included in this inspection. The inspection performed is not intended as a substitute for a seller's disclosure statement.

NOTE: THE INSPECTOR IS NOT REQUIRED TO MOVE FURNITURE, CARPETING, INSULATION, OR OTHER MATERIALS OR BELONGINGS IN ORDER TO PERFORM THE INSPECTION. THIS INSPECTION DOES NOT COVER ITEMS OR CONDITIONS THAT MAY BE DISCOVERED ONLY BY INVASIVE METHODS. NO REMOVAL OF MATERIALS OR DISMANTLING OF SYSTEMS SHALL BE PERFORMED UNDER THIS INSPECTION.

## 2. The following is not within the scope of this inspection:

- a) Building code or zoning ordinance violations
- b) Structural integrity
- c) Geological stability or ground condition of site
- d) System design problems, functional adequacy, operational capacity, quality or suitability for a particular use of items inspected
- e) Termites, wood destroying insects and dry rot
- f) Engineering, scientific or specialized technician tests or readings or evaluations
- g) Fireplace draft
- h) Asbestos, radon, lead, mold or other environmental hazards
- i) Cosmetic items such as minor scratches, scrapes, dents, cracks, stains, soiled or faded surfaces
- j) Home warranties, system warranties and component warranties

Inspection by invasive means and reports covering some of the items (a) through (j) above, are available through this inspection service under separate direction and contract.

## **Inspection Standards**

#### 1. Inspection Standards:

This inspection report expresses the professional opinion of the inspector who prepared this report. The purpose of the inspection is for the customer to be informed of as many conditions as possible within the brief periods of time allotted for the inspection. Customer has no expectation of being notified of all conditions, which are not reported. This inspection service is not responsible for any condition affecting any system or component, which occurs subsequent to the inspection or is intermittent and not detectable during the inspection. This report is based on the standards of the American Society of Home Inspectors (ASHI). A copy of these standards may be obtained from this inspection service.

#### 2. Exclusions:

Excluded is any inspection of any systems or items not included in the Inspection Report including, but not limited to, the following: any information pertaining to manufacturers' recalls of any component, detached buildings or equipment, low voltage systems, swimming pools, saunas, spa, whirlpool, and hot tub systems, electrostatic precipitators or electronic air cleaners or filters, septic systems, any component or system which is underground, private water systems or equipment, wells and well pumps, cisterns, fountains, water quality or volume, water conditioning systems, central vacuum systems, landscaping, irrigation systems, active and passive solar systems, soils or soil contaminations, security systems, and any inspection or testing for any toxic or dangerous substances including asbestos, lead or gases, radon and formaldehyde, other than gases typically used as fuel for home heating systems, or any system or item not included in the Inspection Report.

### 3. Report Prepared For The Customer Exclusively:

The Inspection Report is not intended for use by anyone other than the client. No third party shall have any right arising from the Inspection Report. The Client's request that this Inspection Service release copies of the Inspection Report shall be at Client's risk with respect to the contents of this paragraph. In consideration of the furnishing of the Inspection

Report to third parties, the Client shall agree to indemnify and hold harmless the Inspection Company and its inspectors for all costs, expenses, legal fees, awards, settlements and judgments in any legal proceeding brought by any third party who claims that he/she relied on representations made in such Inspection Report and was damaged thereby.

## **Explanation of Terms**

It is important to have a clear understanding of the terms used in this inspection report. The HOME CONDITION ANALYSIS is conducted with the age of the home and the comparable condition of the neighborhood homes taken into consideration.

#### TERMS:

- <u>ACCEPTABLE</u>: Any item marked, as Acceptable appears to be in usable condition. Cosmetic blemishes and minor damage that does not significantly affect the use of the item or system may be classified as Acceptable.
- ♦ MAINTENANCE: The inspector has determined that the inspected system / item is in need of maintenance in order to prevent further damage or deterioration. Maintenance may be required to provide correct function.
- REPAIR: Items marked Repair appear to be in need of immediate attention. Delay in maintenance or repair of the said items may result in a dramatic shortening of the life expectancy of the item, have immediate negative effect on other related systems, or be a potential safety hazard. Often action is advisable on these items prior to or shortly after moving into the home.
- N/A: Items marked N/A are not covered by this inspection report. N/A does not necessarily indicate the item does not exist, but if it exists the inspector did not or was unable to conduct any inspection of the item at this time. N/A may also indicate not accessible, not available, not addressed, not appropriate or not applicable.

## **Not A Warranty**

There are Home Warranty programs offered through many vendors. We suggest that you discuss these options with your agent.

THIS REPORT IS NOT A WARRANTY. THIS INSPECTION SERVICE ONLY WARRANTS THAT ITS INSPECTION SERVICES WILL BE PERFORMED IN ACCORDANCE WITH THE SCOPE AND THE STANDARDS OF PRACTICE OF THE NATIONAL ASSOCIATION OF HOME INSPECTORS AND THE AMERICAN SOCIETY OF HOME INSPECTORS ONLY. THIS IS A LIMITED AND NON-TRANSFERABLE WARRANTY AND IS THE ONLY WARRANTY GIVEN BY INSPECTION COMPANY. INSPECTION COMPANY MAKES AND CLIENT RECEIVES NO OTHER WARRANTY, EXPRESS OR IMPLIED. ALL OTHER WARRANTIES, INCLUDING WARRANTIES OF MERCHANTABILITY AND FITNESS FOR PARTICULAR PURPOSE, ARE EXPRESSLY EXCLUDED. THIS STATED EXPRESS WARRANTY IS IN LIEU OF ALL LIABILITIES OR OBLIGATIONS OF INSPECTION PERFORMANCE OF THE INSPECTION AND ANY DELIVERY AND USE OF AND RELIANCE ON THE INSPECTION REPORT. CLIENT WAIVES ANY CLAIM FOR CONSEQUENTIAL, EXEMPLARY OR INCIDENTAL DAMAGES, EVEN IF INSPECTION COMPANY HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any dispute, controversy or claim arising out of, or relating to, this agreement or breach thereof shall be submitted to final binding arbitration under the Expedited Arbitration Rules of the National Academy of Conciliators. The decision of the arbitrator appointed there under shall be final and binding and judgment on the award may be entered in any court of competent jurisdiction.

#### Mine Subsidence

Mine subsidence is a fact of life in Western Pennsylvania and is not covered by this inspection. Please contact the PA Department of Mines for an evaluation as to weather mine subsidence insurance is applicable for this property.





This Form is recommended and approved for, but not restricted to use by, the members of the Pennsylvania Home Inspectors Coalition and the Pennsylvania Association of REALTORS® Users are authorized to reproduce unaltered copies of this Home Inspector Compliance Statement for personal or business use in connection with the performance of a home inspection.

For more information about how to obtain additional copies of this form please contact your local REALTOR®□ or home inspector.

## PENNSYLVANIA HOME INSPECTORS COMPLIANCE STATEMENT

## **CLIENT INFORMATION**

Client Name(s): Inspection Property Address:	
	VNOWLEDGMENT out by the home inspector)
I represent that (check one):	
I am full member in good standing of a national home ins of the above property in accordance with the ethical standard Pennsylvania Home Inspection Law.	spection association* and that I will conduct a home inspection s and code of conduct or practice of the association and the
<u> </u>	)R
I have not yet attained full membership in a national hom member in good standing who agrees to be responsible for th conduct a home inspection of the property is accordance with association and the Pennsylvania Home Inspection Law.	e home inspection report by signing the report, and that I will
	A-Z Tech Home Inspections, Inc.
Signature Date	Inspection Co.
Christopher A. Thomas	17 Fosterville Road, Greensburg PA 15601
Inspector Name American Society of Home Inspectors ASHI <b>263647</b>	Address
Association in which membership is held Member No.  Bruce R. Thomas 203847	(724)836-0328 / (724)836-1842
Supervising Inspector's Name & Member No. (if applicable)  Date	Phone / FAX

A national home inspection association is one that: 1) is operated on a not-for-profit basis and is not operated as a franchise; 2) has members in more than 10 states; 3) requires that a person may not become a full member unless the person has performed or participated in more then 100 home inspections and has passed a recognized or accredited examination testing knowledge of the proper procedures for conducting a home inspection; and 4) requires that its members comply with a code of conduct and attend continuing professional educational classes as an ongoing condition of membership.



## **Inspection Findings**

## Note:

Any indication of repair, service or maintenance revealed in this report or verbally at the time of the inspection should be reevaluated by a qualified contractor prior to any final date as indicated in any Real Estate sales agreement. Since this inspection company does not dismantle equipment or perform invasive inspections the contractors subsequent examination may reveal additional required repairs.

	Special request								
Kitc	hen								
1)	Location	Rear							
2)	Floor Cover	⊠Acceptable		Maintenand	се	Re	pair		□N/A
		The floor coveri			en a	rea a	appears to b	e prov	iding adequate
		protection and s							
3)	Under Sink Insp.	⊠Acceptable		Maintenand	се [	Re	pair		□N/A
4)	Drains Appear Clear	⊠Yes		No					□N/A
5)	Stove Exhaust Fan	⊠Acceptable		Repair		No	ne		□N/A
6)	Stove	⊠Electric		]Gas					□N/A
7)	All Elements Work	⊠Yes		]No					□N/A
8)	Controls	⊠Acceptable		Repair					□N/A
9)	Microwave Built in	⊠No		]Yes					□N/A
10)	Microwave Operational	∐Yes		]No					⊠N/A
11)	Oven	⊠Electric		]Gas					□N/A
12)	Oven Operational	⊠Yes		]No					□N/A
13)	Oven Self Cleaning	⊠Yes		]No					□N/A
14)	Built in Unit	⊠No		Yes					□N/A
15)	Oven Door Fit	⊠Yes		No					□N/A
16)	Oven Ventilation	⊠Acceptable		Maintenand	се				□N/A
17)	Counter Tops	⊠Acceptable		Maintenand	се				□N/A
18)	Garbage Disposal	Acceptable		Repair					□N/A
19)	Woodwork	Acceptable		Maintenand	се				□N/A
20)	Drawers/Doors	Acceptable		Repair					□N/A
21)	Dishwasher	Operational			No		Not Operat	ional	□N/A
,		The dishwasher	a	opears to be	wo	rking	g. An on/off	check	of the dishwasher
		was performed t	to	determine if	it is	ope	rational. A f	ull cyc	le check is often not
		possible in the ti	im	e allotted fo	r this	s ins	pection; the	refore	, we cannot comment
		on the full exten	t o	f its function	ıs.				
22)	Trash Compactor	Operational		Yes [	No		Not Operat	ional	⊠N/A
Bati	hroom								
1)	Location Main / Upper floor								
2)	Floor Cover	Acceptable		Maintenand	се [	]Re	pair [	N/A	
3)	Basin (s)	Acceptable		Repair				N/A	
4)	Basin Fixtures	Acceptable		Repair				N/A	
5)	Basin Drain	Acceptable	Ī	Repair				N/A	
6)	Under Sink Inspection	Acceptable	Ī	Maintenand	се Г	Re	pair	N/A	



7)	Shower Tub Shower	Shower / Tub		Stand alone	N/A	
8)	Shower Faucets		Repair		N/A	
9)	Shower Head		Repair		□N/A	
10)	Shower/Tub Enclosure		Maintenance	Repair [	N/A	
11)	Water Resist Wall Cover		Maintenance		N/A	
12)	Caulking Water Exposed Area		Maintenance	☐Repair [	□N/A	
13)	Tub		Repair		N/A	
14)	Tub Fixtures		Repair		N/A	
15)	Tub/Shower Drain		Repair		N/A	
16)	Toilet Bowl		Repair	Loose	N/A	
17)	Toilet Tank		Repair		N/A	
18)	Mildew	⊠No [	Yes		□N/A	
19)	Ventilation	Acceptable [		⊠None	N/A	
						on is necessary to
		prevent mildew a	and to protect wa	alls and ceilings f	rom con	densation damage.
Batl	hroom					
1)	Location Basement					
2)	Floor Cover	⊠Acceptable [	Maintenance	Repair	N/A	
3)	Basin (s)	⊠Acceptable [	Repair		N/A	
4)	Basin Fixtures	⊠Acceptable [	Repair		N/A	
5)	Basin Drain	⊠Acceptable [	Repair		N/A	
6)	Under Sink Inspection		Maintenance	Repair	N/A	
7)	Shower Tub Shower	Shower / Tub	Tub only	Stand alone	N/A	
8)	Shower Faucets	⊠Acceptable [	Repair		N/A.	
9)	Shower Head	Acceptable [	Repair		N/A	
10)	Shower/Tub Enclosure	Acceptable [	Maintenance	Repair	N/A	
11)	Water Resist Wall Cover	Acceptable [	Maintenance	Repair	N/A	
12)	Caulking Water Exposed Area		Maintenance		N/A	
13)	Tub	Acceptable [	Repair		N/A	
14)	Tub Fixtures	Acceptable [	Repair		N/A	
15)	Tub/Shower Drain	Acceptable [	Repair		N/A	
16)	Toilet Bowl	Acceptable [	Repair	Loose	N/A	
17)	Toilet Tank	Acceptable [	Repair		N/A	
18)	Mildew	⊠No [	Yes		N/A	
19)	Ventilation		Repair	□None	N/A	
10)		⊠, toooptable [				
	Ш					
Win	dows					
		<b>Σ</b> Λοοστά-1-1- Γ		□Dene:-	1	□NI/A
1)	Window Wells	Acceptable [	Maintenance			□N/A
2)	Glaze / Caulking Window Pane	Acceptable [	Maintenance	Repair		□N/A
3)	Windows Saraana	Acceptable [	Broken / Crac		laa!:- ::	□N/A
4)	Windows Screens	Acceptable [	Maintenance		issing	□N/A
5)	Dbl. Pane Seals / Insulating Windows	Acceptable [	_Repair	□None		□N/A
						ficiency which may
						ime of this inspection
						e to the conditions
		which may effect condition.	inese types of	williuows we can	not dete	mme actual
6)	Storm Windows	Acceptable [	Repair	None		N/A
6) 7)		Acceptable [				⊠N/A □N/A
7)	Windows Latches/Locks		Maintenance	Repair		

8)	Number of Windows Tested	All Available	
Atti	C		
1)	Access Location	Hallway	
2)	Access Size		□N/A
3)	Attic Area	☑Crawl Through ☐Finished ☐Storage [	□N/A
4)	Type roof structure		Other.
2) 3) 4) 5)	Ventilation	□Acceptable ☑Maintenance □Repair [	□N/A
		Attic areas should be vented with half of the ventilating area n	
		point of the roof and the other half near the eaves. It will be n	
		make modifications in the existing attic ventilation system in the	is home in order
<u></u>	Structural Wood	to achieve maximum desired ventilation.   Acceptable Maintenance Repair	□N/A
<u>6)</u> 7)			N/A N/A
8)	Screens Insulation	☐Acceptable ☐Maintenance ☐None [	IN/A □N/A
0)	Ilisulation	There is insulation in the attic. However, it appears that it may	
		sufficient to provide the desired effect. Insulation limits the vis	
		structural components.	ibility of the
9)	Inaccessible Areas	•	one⊠N/A
10)	Duct Work and Piping		N/A
11)	Attic Evaluated By	☐Entrance ☐Head-Shoulder ☐	N/A
Gar	age		
1)	Type	☐Attached ☐Detached ☐Carport ☒Integral [	□N/A
2)	Size	☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	□N/A
3)	Garage Doors	Acceptable Maintenance Repair None	N/A
3) 4) 5) 6) 7) 8)	Automatic Opener	Acceptable Maintenance Repair None	N/A
5)	Door Springs / Mounts	Acceptable Maintenance Repair	N/A
6)	Spring Safety Cable	Acceptable Maintenance None	N/A
7)	Safety Operation, Opener		N/A
8)	Floor	Acceptable Maintenance Repair	N/A
9)	Plumbing		N/A
10)	Electrical Services	⊠Acceptable	N/A
11)	Heat	⊠No	□N/A
12)	Windows	⊠Acceptable	□N/A
13)	Rafters / Beams	⊠Acceptable	□N/A
14)	Foundation		N/A
15)	Fire Wall / Ceiling / Board	⊠Acceptable	N/A
16)	Fire Door	⊠Yes  □No  □	□N/A
Bas	sement Foundation		
1)	Foundation Type / Material	⊠Block	□N/A
2)	Access (Stairs)	☐ Acceptable ☐ Maintenance ☐ Repair ☐	 ]N/A
3)	Cracks 1/4" Separation	No ☐Yes [	N/A
4)	Moisture / Dampness		□N/A
٠,		Although the basement appeared to be dry at the time of inspe	
		condensation and water penetration are always a possibility.	
		dehumidifier at a minimum is recommended.	
5)	Crawl Space Evaluated by	☐Full entry ☐Head shoulders ☐No access ☐Limited Acces	s ⊡None ⊠N/A

6)	Crawl space condition		Acceptable [	Debris [	Moisture	Ventilation	⊠N/A
7)	Exposed Ducts / Piping	$\boxtimes$	Acceptable [	]Repair [	None		□N/A
8)	Sump / Drain Pump		Acceptable [	Not tested [	_Repair [	None	⊠N/A
9)	Living Area	$\boxtimes$	Yes [	No	-		□N/A
10)	Doors / Windows	$\boxtimes$	Acceptable [	Maintenance [	_Repair [	None	□N/A
			•		•		
Laui	ndry						
	_		V-00 [	JNo [	Donoir	□NI/A	
1)	Washer Hookup		Yes [	No [	Repair	□N/A	
2)	Dryer Hookup		Yes [	]No [ ☑No	Repair	□N/A	
3)	Gas Service	_			laalm.	□N/A	
				ryer service in t			ingements and
4)	Dry (on Floatrical Compies 220)/			e made in orde	r to use a ga		
4)	Dryer Electrical Service 220V		Yes [	]No		□N/A	
5)	Floor Drain		Yes [	No [	Repair	□N/A	
6)	Laundry Basin		Acceptable [	Repair [	None	□N/A	
7) 8)	Dryer Ventilation System		Acceptable [	Repair [	None	□N/A	
8)	Floor Cover		Acceptable [	Maintenance	Repair	□N/A	
9)	Area Ventilation	$\boxtimes$	Acceptable [	]Repair [	None	□N/A	
Wat	er Heater						
1)	Location / Approx. Age	Bas	sement /				
2)	Туре		Gas ⊠Ele	ectric		□N/A	
-,	.,,,,			d that water hea	iters be drair		v to remove
			diment buildup				,
3)	Size Main / Aux. (gal)	40	'				
4)	Evidence of Leaks	ΧI	No Ye	S		□N/A	
4) 5) 6)	Safety Valve		Acceptable [	Maintenance	Repail		
6)	Safety Valve Drain Pipe		Acceptable	Maintenance	None	□N/A	
7)	Installation		Acceptable	Repair	Replac		
_ · /			тоориялого _				
Ноэ	ting System						
	ting System	0.11					
1)	System Type / Location	Oil	Forced Air				
1) 2)	System Type / Location  Manufacturers Information		_				
1)	System Type / Location	$\boxtimes$	Acceptable [	Maintenance	□Repaiı		
1) 2)	System Type / Location  Manufacturers Information	⊠/ Vei	Acceptable [rification of acc	urate temperatı			ostat is not within
1) 2) 3)	System Type / Location  Manufacturers Information  Thermostat Condition	⊠/ Vei	Acceptable [rification of acceptable scope of this is	urate temperatunspection.	ure calibratio	n of the therm	ostat is not within
1) 2)	System Type / Location  Manufacturers Information	Verthe	Acceptable [rification of acceptable [	curate temperatunspection.  Not Tested	ure calibratio ☐Repaii	n of the therm	
1) 2) 3)	System Type / Location  Manufacturers Information  Thermostat Condition	Ver the Ver	Acceptable [rification of acceptable [Acceptable Irification of the	curate temperatous pection.  Not Tested operation of the	ure calibratio ☐Repair e heating sys	n of the therm	ostat is not within
1) 2) 3) 4)	System Type / Location  Manufacturers Information  Thermostat Condition  On / Off Check	Ver the Ver not	Acceptable [rification of acceptable [Acceptable [rification of the swithin the sco	curate temperatunspection.  Not Tested	ure calibratio  ☐Repaile heating systems.	n of the therm  ∩ □N/A stem safety co	
1) 2) 3) 4)	System Type / Location  Manufacturers Information  Thermostat Condition  On / Off Check  Operation Noise	Ver the Ver not	Acceptable [rification of acceptable [rification of the street acceptable content of the street acceptable]	urate temperatunspection. Not Tested operation of the pe of this inspec	ure calibratio ☐Repair e heating sys	n of the therm  N/A stem safety co	
1) 2) 3) 4)	System Type / Location  Manufacturers Information  Thermostat Condition  On / Off Check	Ver the Ver not	Acceptable [rification of acceptable [rification of the street acceptable content of the street acceptable]	curate temperatous pection.  Not Tested operation of the	ure calibratio  ☐Repaile heating systems.	n of the therm  N/A stem safety co	
1) 2) 3) 4)	System Type / Location  Manufacturers Information  Thermostat Condition  On / Off Check  Operation Noise	Ver the not	Acceptable [rification of acceptable [rification of the acceptable content of acceptab	urate temperatunspection. Not Tested operation of the pe of this inspection. Cleaning	Repaire calibratio  □Repaire heating systetion. □Repair	n of the therm  N/A stem safety co N/A N/A N/A g or cleaning.	
1) 2) 3) 4)	System Type / Location  Manufacturers Information  Thermostat Condition  On / Off Check  Operation Noise	Ver the not	Acceptable [rification of acceptable [rification of the acceptable content of acceptab	urate temperatinspection. Not Tested operation of the pe of this inspection.	Repaire calibratio  □Repaire heating systetion. □Repair	n of the therm  N/A stem safety co	
1) 2) 3) 4) 5) 6)	System Type / Location Manufacturers Information Thermostat Condition  On / Off Check  Operation Noise Filter Condition	Ver the Not The	Acceptable [rification of acceptable cuttors within the scondard Acceptable Acceptable Acceptable e heat system in the store is an electre.	urate temperaturs  nspection.  Not Tested operation of the pe of this inspection.  Cleaning filters are in need Yes onic filter syster	Repaire heating systems. Repaire Repaire Repaired of changing which will parts.	n of the therm  N/A stem safety co N/A N/A N/A or Or cleaning. N/A provide years	ntrol switches is
1) 2) 3) 4) 5) 6)	System Type / Location Manufacturers Information Thermostat Condition  On / Off Check  Operation Noise Filter Condition	Ver the Not The ser	Acceptable [rification of acceptable cuttors within the scondard secondard s	urate temperate nspection.  Not Tested operation of the pe of this inspection.  Cleaning filters are in need Yes onic filter system of the sys	Repaire heating systems. Repaire Repaire Repaired of changing which will percentage.	n of the therm  N/A stem safety co  N/A N/A g or cleaning. N/A provide years contact the ma	ntrol switches is  of increased nufacturer for
1) 2) 3) 4) 5) 6)	System Type / Location Manufacturers Information Thermostat Condition  On / Off Check  Operation Noise Filter Condition	Ver the Note of th	Acceptable [rification of acceptable continued in the score of this in the score of the interest of the score	urate temperaturs  nspection.  Not Tested operation of the pe of this inspection.  Cleaning filters are in need Yes onic filter system of the filters must be the sand schedule.	Repaire heating systems. Repaire Repaire Repaired of changing which will percentage. Cing. Verifica	n of the therm  N/A stem safety co  N/A N/A N/A g or cleaning. N/A orovide years ontact the ma	ntrol switches is  of increased nufacturer for
1) 2) 3) 4) 5) 6)	System Type / Location Manufacturers Information Thermostat Condition  On / Off Check  Operation Noise Filter Condition	Ver the Note of th	Acceptable [rification of acceptable crification of the crification of	urate temperate inspection.  Not Tested operation of the pe of this inspection.  Cleaning filters are in need on it filter system of the scope of the scope of the stope of the scope of the scope of the spection.	Repaire heating systems. Repaire Repaire Repaired of changing which will percentage. Cing. Verifica	n of the therm  N/A stem safety co  N/A N/A N/A Or cleaning. N/A Orovide years of the mation of the operation.	ntrol switches is  of increased nufacturer for
1) 2) 3) 4) 5) 6)	System Type / Location Manufacturers Information Thermostat Condition  On / Off Check  Operation Noise Filter Condition	Ver the Note of th	Acceptable [rification of acceptable continued in the score of this in the score of the interest of the score	urate temperaturs  nspection.  Not Tested operation of the pe of this inspection.  Cleaning filters are in need Yes onic filter system of the filters must be the sand schedule.	Repaire heating systems. Repaire Repaire Repaired of changing which will percentage. Cing. Verifica	n of the therm  N/A stem safety co  N/A N/A N/A Or cleaning. N/A Orovide years ontact the mation of the ope	ntrol switches is  of increased nufacturer for

10)	Insulation	⊠Acceptable		None		Repai	r [	N/A	
11)	Non-Heated Living Area	None							
12)	Service Notes / Filter Size								
13)	Condition	Acceptable		Evaluate [					
									st once every year.
		This system is i	n n	eed of ann	ual ma	intenance	e. Ple	ease se	ee "Note" above.
Air	Conditioning								
1)	System Type / # of Units / Location	Compressor /1	/ F	Rear					
2)	Manufacturer Specifications / Size								
3)	Systems Operational	☐Yes ☐	No	⊠N	lot Test	ted	$\square$ N/	Α	
4)	Service Records Noted	None							
5)	Areas Not Serviced	None							
6)	Ambient Temp at Time of Insp.								
7)	Air Temp. At Outlet								
	-								
Elec	ctrical Service								
1)	Service Size (Amps)	☐Under 80		80 to 100	⊠100 t	o 200 [	Ov	er 200	□N/A
2)	Service Voltage	⊠110-220		110 only [	Othe	r			□N/A
3)	Over Current Devices	⊠Breakers		Fuse [	Fuse	& Breake	ers		□N/A
		Overload prote	ctio	n is provid	ed by b	reakers t	for thi	s struc	ture.
4)	Service to Panel	Copper		Alum.		er/Alum.	□Re	pair	□N/A
5)	Panel to Structure	⊠Copper		Alum.		er/Alum.	□Re	pair	□N/A
6)	Panel Cover	⊠Acceptable		Maintenan	ce 🔲 F	Repair			□N/A
7)	Panel Cover Removed	⊠Yes		No					□N/A
		The face plate of							
		electrical panels		provide th	e inspe	ector visua	al acc	ess for	r verification of
	Daniel Oracilifica	existing condition							
8)	Panel Condition	Acceptable	Ш	Maintenan	се	Repair			□N/A
9)	Panel / Sub Panel Location  Type of wire	Utility room ⊠Romex		DV 🗆 Vna	b & Tu	bo D Mi	٠٠٠٩٢	7 Othou	- ΠNI/Λ
10)	71	Acceptable					xed	<u></u> Other	r □N/A □N/A
11)	Wire - Over Current Compatibility			Evaluate		Repair	vicos	annoa	∟ln/A r to be compatible as
		seen from the p				ection de	vices	appea	i to be compatible as
12)	Proper Receptacle Grounding				otou.				□N/A
12)	Troper Recopiacie Grounding				ed the	three-pro	na fe		10 volt electrical
									at were not correctly
									ered condition may
		exist.				•			·
13)	G.F.I Outlets	⊠Yes		Pre-Date		est OK [			□N/A
		Current electric							
					is a pot	tential da	nger (	of elect	trical shock. This
		property has G.							
14)	Service Ground Verified	⊠Yes		No					□N/A
45	D ( ( 1) ) ( ( ) ( ) ( ) ( ) ( ) ( ) ( )	The main groun	<u>id to</u>		ce has	been veri	tied.		
15)	Bare (metal) Wires Visible	⊠No	빝	Yes					□N/A
16)	Improper Splices / Junctions	No	닏	Yes					□N/A
17)	Improper Wire Protection / Routing	⊠No ⊠Na	=	Yes					□N/A
18)	Double taps	⊠No ⊠Na	=	Yes					□N/A
19)	Uncovered Splice Boxes	⊠No	_	Yes Ves					□N/A



There are one or more receptacles with "hot, neutral reversed" in this home. In short the receptacle is wired backwards. This condition can cause problems with some sensitive electronic equipment and increases shock hazard. I suggest a qualified electrician be consulted.

			illied electrolari de doribalted.	
Plui	mbing			
_1)	Size Service to Structure	☐3/4 inch	]1 inch	
2)	Structure Pipe Material	Copper	Plastic □Galvanized ⊠Mixed □Other □N/A	
3)	Waste Pipe Material	Copper	Plastic □Galvanized ⊠Mixed □Other □N/A	
4)	Plumbing Vent Material	Copper	Plastic □Galvanized ⊠Mixed □Other □N/A	
5)	Plumbing Vent Condition	⊠Acceptabl	☐Maintenance ☐Repair ☐N/A	
6)	Pipe Rumble Noise	⊠No	Yes N/A	
7)	Surge Bangs	⊠No	Minor Repair N/A	
8)	Encrustation Evident	⊠No	Yes N/A	
9)	Hot Water Pipe Insulation	⊠No	Yes N/A	
10)	Evidence of Supply Leaks	⊠No	Yes N/A	
11)	Evidence of Drain Leaks	⊠No	Yes N/A	
12)	Faucets Leak	⊠None	One More N/A	
13)	Main Water shut off Location	Meter		
14)	Interior Water Flow	⊠Acceptabl	☐Maintenance ☐Repair ☐N/A	
15)	Exterior Water Flow	Acceptabl	☐Maintenance ☐Repair ☐N/A	
<b>Utili</b> 1)	ity Services  Electrical Service	□Under Gro	ınd ⊠Overhead	
2)	Gas Service	None	Natural Other N/A	
3)	Gas Odors	Yes	⊠No □N/A	
3)	Main Gas shut off Location	N/A		
5)	Overhead Service Lines	Acceptabl	☐Maintenance ☐Repair ☐N/A	
6)	Fuel Storage Tank	Yes	□No □N/A	
7)	Fuel Storage Underground	Yes	□No □Part Exposed□Unknown □N/A	
,	5 - 5		eaks may exist	
8)	Fuel in Tank	⊠Yes	□No □Not Determinable □N/A	
9)	Fuel Tank Condition	Acceptabl		
10)	Fuel Tank Plumbing	Acceptabl		
	П			
<b>Fire</b> 1)	Place / Wood Stove Fire Place (s) Wood Stoves (s)	There is a so be in Accept	☐Cleaning ☐Repair ☐N/A d-fuel heating system/fireplace (s) in this home that appe ble condition. This inspection does not cover code cleara	ances
2)	Exterior Chimney (s) Condition		installation. If additional information and certification is despection service.  ☑Maintenance ☐Repair ☐N/A	
<i>-)</i>	Extends diminity (3) condition	Inspection h	s revealed that the chimney requires some preventive o insure proper condition.	
3)	Type Fireplace	Masonry	Metal insert ☐Wood stove ☐Other ☐N/A	
4)	Flue Dampers	Acceptabl	☐Maintenance ☐Repair ☐N/A	
5)	Flue Condition	Acceptabl	☐Cleaning ☐Repair ☐N/A	
,			s not visible using visual inspection protocols. Contact a	
			ney specialist for further details.	

6)	Spark Arrester	⊠Acceptable	☐Maintenance [	□Repair	□None
	cement chimney caps on both chimneys allified masonry or chimney contractor.		o crack and deter	iorate. It is recomr	nended they be evaluated
<u>~) qe</u>	dimed madering of driminely demination.				
Env	ironmental Survey				
1)	Asbestos Warning (1930-1980)	□No	⊠Yes	□N/	'A
,	- ,				ity this structure may
					s of products incorporated
					e will be glad to provide
					and testing possible the E.P.A. guidelines for
		this type of st		ii dooordanoe witii	the E.F. J. t. galdelines for
2)	Visual Material Suspect Asbestos	⊠No [	_Yes	N/	'A
3)	Suspect Samples Taken	⊠No		N/	'A
4)	Describe Possible Asbestos Material/Location				
5)	Mold, Mildew, Fungus	Not visible	e 🗌 Visible	N/	/A
					e visible under current
		•	oores are always p	oresent. Under cer	tain conditions the spores
6)	Radon Warning	can grow. ⊠Yes		N/	/Λ
0)	Nadon Warning		s naturally occur		nment in harmless
					ercolates though the
					through fissures or
					concentrated, due to lack
					Agency and the Surgeon
					idon. Your inspection I testing in accordance
				on Agency protoc	
7)	Lead in Material Warning (Prior 1978)		⊻Yes	N/	
·					974, the warning is in
					the Federal Department of
					can be present in a house
					rimary danger would be to lead-based paint. Your
					tion and test paint samples
			re for lead contam		
8)	Lead in Water Warning	⊠No	Yes	N/	'A
Buil	ding Perimeter Exterior				
1)	Visible Cracks	XYes - Cracks	are visible in the	foundation system	. Most cracks are normal
• ,	Tielele Graeke			to the curing proce	
2)	Evidence of Separation over 1/4"	⊠No	Yes	<u> </u>	□N/A
3)	Evidence of Differential Drift	⊠No	Minor [	Repair	□N/A
4)	Site Drainage	Acceptable	Maintenance	Repair	□N/A
5)	Evidence of Erosion	⊠No	Minor	Repair	□N/A
6)	Proper Clearance Earth to Wood	⊠Yes	□No		□N/A
7)	Vegetation Clear from Structure	Yes	No	- Donoir	□N/A
8)	Retaining Walls	Acceptable The retaining w	Maintenance [ alls will require m		□N/A re their proper condition.
9)	Driveway Material	Concrete		⊠Gravel  □Othe	
10)	Driveway Condition	Acceptable	☐Maintenance	Repair	□N/A
11)	Walkway Material	⊠Concrete	Gravel	☐Masonry ☐Othe	
Prop				-	

12

13) Steps Material	12)	Walkway Condition	⊠Acceptabl	e [	Maintenance	Repair	□N/A	
15  Flat Surface Material	13)	Steps Material	⊠Concrete		Masonry		- □N/A	
16    Siding Condition	14)	Steps Condition	⊠Acceptabl	e [	Maintenance	Repair	□N/A	
17)   Painted Surfaces	15)	Flat Surface Material	Brick					
18)   Cauking Structure	16)	Siding Condition	⊠Acceptabl	e [	Maintenance	Repair	□N/A	
	17)	Painted Surfaces	Acceptabl	е		Repair	□N/A	
19  Eave / Soffit Areas	18)	Caulking Structure	Acceptabl	e [	Maintenance	Repair	□N/A	
20)   Fascia Boards	19)	·	Acceptabl	е	Maintenance	Repair	□N/A	
21)   Trim	20)	Fascia Boards	Acceptabl	e [	Maintenance		□N/A	
Patios / Decking / Porches	21)	Trim	Acceptabl	е		Repair	□N/A	
Patios / Decking / Porches	22)	Exterior Doors	Acceptabl	е	Maintenance	Repair	 ∏N/A	
Deck / Porch Material								
		<u> </u>	□Wood	Б	Concrete	□Other	ΠΝ/Δ	
3   Deck / Porch Railings								
Deck / Porch Foundation								
Mood Post / Pillars								
Name								
Masonry Patio								
Cover Location / Material							<u> </u>	
1) Cover Location / Material	0)			<u> </u>			DIVA	
Type								
3) Moss / Mildew								
A								
Solitor   Soli								
6) Cover Material Condition					101			
7) Ridges					Renair			
Solution   Solution								
9) Flashing / Caulking								
10)   Vents / Covers								
11) Gutters		·						
12  Gutter Material								
13)   Down Spouts			_					
14)       Drains Splash Blocks       Acceptable       Maintenance       Repair       N/A         15)       Roof Inspect From Underside       Yes       No       N/A         16)       Exposed Rafters / Sheathing       Yes       N/A         17)       Light through       No       Yes       N/A         18)       Indications of Leaking       No       Yes       N/A         19)       Soft Spots       No       Yes       N/A         20)       Skylight       Acceptable       Maintenance       Repair       N/A         21)       Estimated Roof Life Expectancy With Proper Care & Maintenance       10 yrs +       Valuated By         22)       Evaluated By       Walk Surface       Roof Edge       Ground       Not Visible       N/A         The roof cover was evaluated from the ground, using visual aid.								
15) Roof Inspect From Underside								
16)       Exposed Rafters / Sheathing       Yes       No       N/A         17)       Light through       No       Yes       N/A         18)       Indications of Leaking       No       Yes       N/A         19)       Soft Spots       No       Yes       N/A         20)       Skylight       Acceptable       Maintenance       Repair       N/A         21)       Estimated Roof Life Expectancy With Proper Care & Maintenance       10 yrs +       22)         Evaluated By       Walk Surface       Roof Edge       Ground       Not Visible       N/A         The roof cover was evaluated from the ground, using visual aid.		•						
17)     Light through     No     Yes     N/A       18)     Indications of Leaking     No     Yes     N/A       19)     Soft Spots     No     Yes     N/A       20)     Skylight     Acceptable     Maintenance     Repair     N/A       21)     Estimated Roof Life Expectancy With Proper Care & Maintenance.     10 yrs +       22)     Evaluated By     Walk Surface     Roof Edge     Ground     Not Visible     N/A       The roof cover was evaluated from the ground, using visual aid.		·						
18) Indications of Leaking       No       Yes       N/A         19) Soft Spots       No       Yes       N/A         20) Skylight       Acceptable       Maintenance       Repair       N/A         21) Estimated Roof Life Expectancy With Proper Care & Maintenance.       10 yrs +       Evaluated By         22) Evaluated By       Walk Surface       Roof Edge       Ground       Not Visible       N/A         The roof cover was evaluated from the ground, using visual aid.		·						
19) Soft Spots				<u> </u>				
20) Skylight		•		<u>L</u>				
21) Estimated Roof Life Expectancy With Proper Care & Maintenance. 10 yrs + ☐ 22) Evaluated By ☐ Walk Surface ☑ Roof Edge ☑ Ground ☐ Not Visible ☐ N/A The roof cover was evaluated from the ground, using visual aid.				<u> </u>		□ Popoir		
22) Evaluated By ☐ Walk Surface ☑ Roof Edge ☑ Ground ☐ Not Visible ☐ N/A The roof cover was evaluated from the ground, using visual aid.							⊠IN/A	
The roof cover was evaluated from the ground, using visual aid.							Jo DN/A	
	22)	Evaluated by						
The fool cover was evaluated at the fool edge.							visual alu.	
				~ · · · · · · ·	io ovaluatou at	uio iooi oddo.		

## Structure

1)	Description	Ranch
2)	Date Built	1972
3)	Type Construction	□ Frame  Brick Veneer  Masonry  Combination  Other
4)	Floor Construction	□ Dimensional Joist □ Truss □ Wood I beam □ Concrete □ Other
5)	Wall Construction	
5) 6)	Ceiling Construction	□ Dimensional Joist □ Truss □ Wood I beam □ Concrete □ Other
7)	Interior Stairs	⊠Acceptable ☐ Maintenance ☐ Repair ☐ N/A
8)	Stair Rails	⊠Acceptable ☐ Maintenance ☐ Repair / Missing ☐ N/A
9)	Remodel/Modernization Evident	□No ⊠Yes □N/A
10)	Repairs Evident	□No ⊠Yes □N/A
11)	Insulating Rating Evident	⊠No □Yes □N/A
12)	Insulation type	None visible
13)	Smoke Detectors	⊠Acceptable
		Smoke detectors should be tested once each month.
14)	Alarm/Security System	⊠None
15)	Exterior Chimney (s) Condition	⊠Acceptable
16)	Type Chimney	
17)	Chimney liner	□ Clay tile    □ Metal    □ Unlined Masonry    □ Undetermined    □ Other    □ N/A
18)	Furniture/Storage	□Average □Light □Vacant □Heavy □N/A
		The home was empty of furniture and/or storage items at the time of
-		inspection.
Ge	neral remarks and sugges	tions:

Wood Destroying Insect Inspection Report on page 2.			Notice: Please read important consumer information		
Section I. General Information Company's Business		ness Lic. No.	Date of Inspection		
Inspection Company, Address, & Phone <b>A-Z Tech Home Inspections, Inc.</b>	BU8021	arty Inspected			
36 E. Tacoma Ave		erty inspected			
Latrobe, PA 15650 (724)836-0328 Inspector's Name, Signature & Certification, Registration	l n, or Lic. #402716		Structure(s) inspected:		
Bruce R. Thomas			Single Home		
Bruce & Thomas					
Section II. Inspection Findings This report is is not to be construed as a guarantee or warranty again inspection of the readily accessible areas of the stru	st latent, concealed	l, or future infes			
A. No Visible evidence of a wood destroying insect infestation was observed.  B. Visible evidence of a wood destroying insect infestation was observed as follows:  1. Live insects: (description & location):					
Do Dood by a discount of the shall state		-!!(-!!t'	O Location)		
2. Dead Insect, insect parts, frass, shelter tube	es, exit noies, or sta	aining (description	on & location):		
☐ 3. Visible damage from wood destroying in	nsects was noted	l as follows (de	escription and location):		
Note: This is not a structural damage report. If box	B above is check	ed it should be	understood that some degree of damage, including		
hidden damage, may be present. If any questions aris	se regarding dama	ge indicated by	this report, it is recommended that the buyer or any		
interested parties contact a qualified structural profession.  Yes No It appears the structure (s) or a portion to			age and the need for repairs. reated.  Visible evidence of possible previous treatment		
The inspecting company can give no assurances with re should be contacted for information on treatment and ar					
Section III Recommendations					
	ction it is checked)				
Recommend treatment for the control of:					
Section IV. Obstructions & Inaccessible Areas The Following areas of the structure(s) inspected were obstructed or inaccessible:  Basement 1,3,4,9  The inspector may write out obstructions or use the following optional key:					
Crawl Space			1. Fixed ceiling 13. Only visual access 2. Suspended ceiling 14. Cluttered conditions		
Main Level	· · · · · · · · · · · · · · · · · · ·		3. Fixed wall covering 15. standing water 4. Floor covering 16. dense vegetation		
Attic 10			5. Insulation 17. exterior siding		
Garage 1,3 6. Cabinets or shelving 18. Window well 19. wood pile			7. Stored items 19. wood pile		
Exterior 17 8. Furnishings 20. snow 9. Appliances 21. unsafe conditions			9. Appliances 21. unsafe conditions		
Porch					
Addition 12. No access beneath 24. Duct work, plumbing and / or wiring					
Other					
Section V Additional Comments and Attachments (t	hese are an integra	I part of the rep	ort)		
Attachments					
	Seller	Signature	of Buyer. The undersigned hereby acknowledges		
acknowledges that all information regarding W.D.I infestation, damage, rece		receipt of a co	receipt of a copy of both page 1 and page 2 of this report and understands the information reported.		
X	x				

Form NPMA-33 (9/01/04) ©2004 National Pest Management Association. All Rights Reserved. No reproduction of this form is permitted without the express permission of NPMA Form NPCA-1 is obsolete after 12/31/04

Page 1 of 2

# Important Consumer Information Regarding the Scope and Limitations of the Inspection

Please read this entire page as it is part of this report. This report is not a guarantee or warranty as to the absence of wood destroying insects nor is it a structural integrity report. The inspector's training and experience do not qualify the inspector in damage evaluation or any other building construction technology and/or repair.

- 1. About the inspection: A visible inspection was conducted in the readily accessible areas of the structure(s) indicated (See Page 1) including attics and crawlspaces which permitted entry during the inspection. The inspection included probing and/or sounding of unobstructed and accessible areas to determine the presence or absence of visual evidence of wood destroying insects. The WDI inspection firm is not responsible to repair any damage or treat any infestation at the structure(s) inspected, except as may be provided by separate contract. Also wood destroying insect infestation and/or damage may exist in concealed or inaccessible areas. The inspection firm cannot guarantee that any wood destroying insect infestation and/or damage disclosed by this inspection represents all of the wood destroying insect infestation and/or damage which may exist as of the date of the inspection. For purposes of this inspection, wood destroying insects include: termites, carpenter ants, carpenter bees and reinfesting wood boring beetles. This inspection does not include mold, mildew or noninsect wood destroying organisms. This report shall be considered in valid for purposes of securing a mortgage and/or settlement of property transfer if not used within ninety (90) days from the date of inspection. This shall not be construed as a 90-day warranty. There is no warranty, expressed or implied, related to this report unless disclosed as required by state regulations or a written warranty or service agreement is attached.
- 2. **Treatment Recommendation Guidelines regarding Subterranean Termites:** FHA and VA require treatment when any active infestation of subterranean termites is found. If signs of subterranean termites --- but no activity --- are found in a structure that shows no evidence of having been treated for subterranean termites in the past, then a treatment should be recommended. A treatment may also be recommended for a previously treated structure showing evidence or subterranean termites but no activity if there is no documentation of a liquid treatment by a licensed pest control company within the previous five years unless the structure is presently under warranty or covered by a service agreement with a licensed pest control company.
- 3. **Obstruction and Inaccessible Areas:** No inspection was made in areas which required the breaking apart or into, dismantling, removal of any object, including but not limited to: moldings, floor coverings, wall coverings, siding, fixed ceilings, insulation furniture, appliances, and/or personal possessions, nor were areas inspected which were obstructed or inaccessible for physical access on the date of the inspection. Your inspector may write out inaccessible areas or use the key in Section IV. Crawl spaces, attics, and/or other areas may be deemed inaccessible if the opening to the area is not large enough to provide physical access for the inspector or if the ladder was required for access. Crawl spaces (or portions thereof) may also be deemed inaccessible if there is less than 24 inches of clearance from the bottom of the floor joists to the surface below. If any area which has been reported as inaccessible is made accessible, the inspection company may be contacted for another inspection. An additional fee may apply.
- 4. Consumer Maintenance Advisory Regarding Integrated Pest Management for Prevention of Wood Destroying Insects. Any structure can be attacked by wood destroying insects. Homeowners should be aware of and try to eliminate conditions which promote insect infestation in and around their structure(s). Factors which may lead to wood destroying insect infestation include: earth to wood contact, foam insulation at foundation in contact with soil, faulty grade, improper grading, firewood against structure(s), insufficient ventilation, moisture, wood debris in crawlspace, wood mulch or ground cover in contact with the structure, tree branches touching structure(s), landscape timbers and wood decay. Should these or other conditions exist, corrective measures should be taken in order to reduce the chances of infestation by wood destroying insects and the need for treatment.
- 5. Neither the inspecting company nor the inspector has had, presently has, or contemplates having any interest in the property inspected.

Form NPMA-33 (9/01/04) ©2004 National Pest Management Association. No reproduction of this for is permitted without the express permission of NPMA, Form NPCA-1 is obsolete after 12/31/04.



17 Fosterville Road Greensburg PA 15601 (724)836-0328 Chris@a-ztech.us www.a-ztech.us

## **Well flow Test Report**

This report contains confidential information and is supplied solely for use by			
Client Information:	Property:		
	1 Topolty.		
<u>I</u>			

<u>Criteria:</u> The flow readings were taken from The septic system test was conducted at the same time as the water flow test. The tests were started at M and continued as follows:

Beginning Meter Reading: 1895

		Meter			
Time On	Time Off	Reading	Gallons	Flow Time	GPM
14:02	14:17	1962	67	15	4.47
14:27	14:42	2075	113	15	7.53
14:52	15:13	2201	126	21	6.00
15:23	15:40	2322	121	17	7.12
15:53	16:09	2443	121	16	7.56
				Total Flow	Average
			Total	Time in	Gallons
			Gallons	Minutes	Per Minute
			548	84	6.54

The flow of any well depends a great deal on the type of pump, depth of the well, size of the plumbing as well as the amount of flow into the well.

The results of this test are valid for the date and time of the test only. There is no warranty either expressed or implied.

Respectfully,

Bruce R. Thomas

Bruce & Thomas

President



17 Fosterville Road Greensburg PA 15601 (724)836-0328 Chris@a-ztech.us www.a-ztech.us

## PRIVATE WASTE DISPOSAL SYSTEM INSPECTION CHECKLIST

Name:
INTERVIEW WITH OWNER
Name: Inspection Date:
Address:
Age Of House: 46 No. Of Bedrooms: 3 Age Of System: 46 Size Of Tank: UNK
When Was The System Last Cleaned? UNK By Whom?
Number Of Occupants: 0 Adults: 0 Children: 0 Number Of Toilets 2
Bath Tubs / Showers: 2 Do The Drains Empty Slowly: NO
Was There Ever A Backup: UNK Type Of System: Septic Tank Sand Mound Other
Location Of System: UNK
Condition Of The Leach Field UNK
Any Odors From The System: UNK Where: UNK
Do You Know Of Any Changes That Could Affect The Operation Of The System: UNK
Are You Satisfied With The Functioning Of Your System: UNK
Was The Property Vacant At The Time Of Inspection: YES
If Yes, Estimate Length Of Time: UNK Is There A Garbage Disposal: NO
The above information was gathered from a credible source but is not guaranteed. The
information below is provided by the inspector.
Observations: No dye or septic breakout was observed during this inspection.
Dye Test Administered: Yes Time: 1400 Amount Of Water: 548 gals
Location Of Breakout: N/A
Recommendations: Cleaning: Repairs:
Other:
OWNER / OCCUPANT: DATE:
INSPECTOR: Bruce & Thomas DATE:

A septic system dye test is only intended to assess the viability and function of the leach field. Maintenance is required for any septic system regardless of the design or installation. Additional information is available from this inspection company upon request of from your local Penn State Extension office or PA DEP.

\*\*\*\* The inspection and report are not intended or to be used as a guarantee or warranty, expressed or implied, regarding the adequacy, performance or condition of any inspected structure, item or system. This inspection does not include or cover buried or inaccessible components of the inspected system(s). The inspection and report are valid only for the time and date the inspections were performed. \*\*\*\*

## Your Notes

## **Summary of Potential Concerns**

In the opinion of the inspector the following items may be of concern to you in the future. This section of the report is not intended to fulfill any Real Estate agreement requirements since I have not seen and do not consult on such agreements. If you have any question as to whether the items below are a concern with respect to your agreement, please consult your Real Estate agent or Attorney.

These items are listed without reference or estimates for cost of repair.

This section is not a substitute for the rest of the report and may not contain an item that may be of concern to you that is explained further in the full report.

### Note:

Any indication of repair, service or maintenance revealed in this report or verbally at the time of the inspection should be reevaluated by a qualified contractor prior to any final date as indicated in any Real Estate sales agreement. Since this inspection company does not dismantle equipment or perform invasive inspections the contractors subsequent examination may reveal additional required repairs.

## Bathroom - Upper level

Ventilation

*None* - This bath area is not properly ventilated. Proper ventilation is necessary to prevent mildew and to protect walls and ceilings from condensation damage.

## Attic

**Access Size** 

None - An access for the attic area was not located or does not exist. Inspection of the attic is suggested. An access should be established if one does not exist. Access size should be a minimum of 14 inches x 22 inches.

#### Laundry

Gas Service

*No* - There is no gas dryer service in the laundry at this time arrangements and installation must be made in order to use a gas dryer.

## Heating System

**Filter Condition** 

Cleaning - The heat system filters are in need of changing or cleaning.

## Heating System

Condition

**Service -** All heating systems should be cleaned and "tuned" at least once every year. This system is in need of annual maintenance. Please see "Note" above.

#### Electrical Service

#### **Hot Neutral Reversed**

There are one or more receptacles with "hot, neutral reversed" in this home. In short the receptacle is wired backwards. This condition can cause problems with some sensitive electronic equipment and increases shock hazard. I suggest a qualified electrician be consulted.

## **Environmental Survey**

Asbestos Warning (1930-1980)

Yes -Based on the age of this home, there is a possibility this structure may contain asbestos. Asbestos was used in hundreds of products incorporated in residential construction. Your inspection service will be glad to provide additional services and information on identifying and testing possible asbestos containing materials in accordance with the E.P.A. guidelines for this type of structure.

## **Environmental Survey**

**Radon Warning Geographical Indication** 

Yes -Radon gas is naturally occurring in our environment in harmless quantities. The danger occurs when the gas percolates though the ground and enters a tightly enclosed structure through fissures or cracks in a foundation. The gas can become concentrated, due to lack of ventilation. The Environmental Protection Agency and the Surgeon General recommend all homes be tested for radon. Your inspection service can provide additional information and testing in accordance with Environmental Protection Agency protocols.

## **Environmental Survey**

Lead in Material Warning (Prior 1978)

Yes -Lead base paint was in common use until about 1974, the warning is in effect for homes built prior to 1978. According to the Federal Department of Housing and Urban Development, a lead hazard can be present in a house of this age from old paint. It is believed that the primary danger would be to small children who may somehow ingest chips of lead-based paint. Your inspection service may provide additional information and test paint samples in this structure for lead contaminate.

## Structure Perimeter Exterior

**Retaining Walls** 

Maintenance - The retaining walls will require maintenance to insure their proper condition.

## Fire Place / Wood Stove

Maintenance - Inspection has revealed that the chimney requires some preventive maintenance to insure proper condition.

## Fire Place / Wood Stove

#### Comment

The cement chimney caps on both chimneys are beginning to crack and deteriorate. It is recommended they be evaluated by qualified masonry or chimney contractor.

#### **Attic**

#### **Ventil**ation

Maintenance - Attic areas should be vented with half of the ventilating area near the high point of the roof and the other half near the eaves. It will be necessary to make modifications in the existing attic ventilation system in this home in order to achieve maximum desired ventilation.

Attic

## Insulation

Maintenance - There is insulation in the attic. However, it appears that it may not be sufficient to provide the desired effect. Insulation limits the visibility of the structural components.

## **Sketch or Pictures**

May not be needed for this property. (Is not to scale)



Aerial view of the roof structure



Basement fireplace chimney. It is recommended that both chimneys be evaluated by a qualified masonry or chimney contractor. The cement chimney caps are deteriorating. This can lead to water intrusion and damage to the bricks.



The light in the basement bathroom shower should have a water resistant cover installed prior to use of the shower.



Furnace chimney.



The attic hatch was nailed and painted shut making the attic inaccessible at the time of the inspection. Property:



Main electric panel.



Electric meter.



Well cistern.



Hot/ neutral reverse receptacle in the basement laundry area.



Water heater and well pump equipment.



Above ground well head cover.

36 E. Tacoma Ave Latrobe, PA 15650 (724)836-0328 Chris@a-ztech.us

www.a-ztech.us



Oil furnace. It is recommended the furnace be serviced by a qualified HVAC technician to maximize its economic life.





A/C Unit. The A/C unit should also undergo routine service to ensure that it is in full working order.



Underground oil tank fill tubes.



Walk out basement door. The retaining walls and roof around this entrance are in need of maintenance or repair.



Rear view of the home.



Reference photo of the attic structure.



Eave vents. It is recommended the insulation be pulled back from the eave vents to improve the ventilation of the attic.